

Technical drawing of a square nut showing three views: front, side, and top. The dimensions are labeled as follows:

- A**: Total height of the nut.
- B**: Width of the base of the nut.
- C**: Height of the base of the nut.
- D**: Width of the top flange of the nut.
- E**: Thickness of the top flange of the nut.
- F**: Width of the base of the nut (same as B).
- G**: Height of the base of the nut (same as C).
- P**: Thickness of the top flange of the nut (same as E).

М	КОД	Р	С	Ф	А	Г	В	Д	Е	Размер отверстия
Гайка клетевая (кузовная квадратная) - типоразмер 2										
М4	М4-2В	1,2 - 1,6	9	12,2	12	6	11,4	7,2	0,4	Размер Посадочного отверстия 8,3 x 8,3
	М4-2С	1,7 - 2,5	9							
М5	М5-2В	1,2 - 1,6	8							
	М5-2С	1,7 - 2,5	9							
М6	М6-2В	1,2 - 1,6	8							
	М6-2С	1,7 - 2,5	9							
	М6-2D	2,6 - 3,5	10							
Гайка клетевая (кузовная квадратная) - типоразмер 3										
М5	М5-3А	0,7 - 1,6	8,5	13,2	13,1	6,3	11	6,5	0,4	Размер Посадочного отверстия 9,0 x 9,0
	М5-3В	1,7 - 2,7	9,5							
М6	М6-3А	0,7 - 1,6	8,5							
	М6-3В	1,7 - 2,7	9,5							
Гайка клетевая (кузовная квадратная) - типоразмер 4										
М5	М5-4А	0,7 - 1,6	8,6	13,5	13,1	6,3	11	6,5	0,4	Размер Посадочного отверстия 9,5 x 9,5
	М5-4В	1,7 - 2,7	9,6							
М6	М6-4А	0,7 - 1,6	8,6							
	М6-4В	1,7 - 2,7	9,6							
	М6-4С	2,8 - 3,8	11							
Гайка клетевая (кузовная квадратная) - типоразмер 5										
М8	М8-5А	0,7 - 1,7	10	16,6	16,4	7,8	15,5	10,6	0,4	Размер Посадочного отверстия 12,3 x 12,3
	М8-5В	1,8 - 3,2	12							
	М8-5С	3,3 - 4,7	14							
М10	М10-5А	0,7 - 1,7	10							
	М10-5В	1,8 - 3,2	12							